

## SITE PHOTOS



View at the subject property from the foreshore



Southwest view – Boat lift remaining from the previous moorage



Southeast view -Gravel and cobble beach substrates



Northwest view along the foreshore to the boat lift-rock, riparian condition